



Safety Notice 012/19

23 August 2019

Distributed to:

- Chief Executives
- **Directors of Clinical** Governance
- **Director Regulation and Compliance Unit**

Action required by:

- Chief Executives
- **Directors of Clinical** Governance

We recommend you also inform:

- Heads of departments
- **Directors of Medical**
- Services Directors of Pharmacy
- Directors of Nursing and Midwiferv
- **Directors of Emergency** Departments
- Directors of Critical Care Units

Expert Reference Group

Content reviewed by:

- · Office of the Chief Health Officer, MoH
- Chief Pharmacist Unit, MoH
- Clinical Excellence Commission

Clinical Excellence Commission

Tel. 02 9269 5500 Fax. 02 9269 5599

Email: CEC-MedicationSafety@health. nsw.gov.au

Internet Website: http://www.health.nsw.gov .au/sabs

Intranet Website http://internal.health.nsw.g ov.au/quality/sabs/

Review date

23 August 2020

Link adrenaline (epinephrine) 1 in 10,000 prefilled syringe - device failure

Background

An incident report has been received regarding the failure of the Link brand of adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL. This product is indicated for use as an adjunct in the management of cardiac arrest.

The tip of a Link adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL was reported to be blocked resulting in the liquid being unable to be expelled from the syringe. Another Link adrenaline (epinephrine) prefilled syringe was then used without issue. It was reported that a compatible connector device was in use, and that user error was not a conduting factor.

Reports from South Australia Health have indicated that blochage nave occurred in the tip of the syringe and cannot be seen without removing the syringe cap and the interlink connector on the end of the syringe. Similar-isolated incidents have been received in the W Incident Information Management System in 2016, 2017 and 2018.

In addition to the incident described above, families should be alert to the fact that that not all connector systems are directly compatible whether Link adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL. In 2017 Link distributed a Safety lert rearrange of this issue. Facilities are advised to only use compatible connector and a aptor system with this prefilled syringe.

As a blockage is thought to have write while using a compatible connecter, facilities using the Link adrenaline (epinephrine) prefied syring should ensure the availability of additional stock or alternative adrenaline (epine prine) products for emergency situations.

Facilities should conduct a local isk a sessment to determine the most appropriate adrenaline the management of cardiac arrest. This should include an (epinephrine) product for upper assessment of any connectors use to ensure that they are compatible with any prefilled adrenaline (epinephrine) symples.

Further Incorporation

RENALINE-LINK 1:10,000 1mg/10mL adrenaline (epinephrine) acid SAF tar ate injection DP pre-filled syringe AUST R 210672

actions by Local Health Districts/Networks Sugge

- 1. Distribute this notice to all relevant staff and all clinical departments.
- Assess usage of the Link adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL in each facility, 2. ensuring all locations of stock are identified.
- Conduct a risk assessment to determine the most appropriate adrenaline (epinephrine) product for use in 3. cardiac arrest. This should include an assessment of any connectors in use to ensure that they are compatible with any prefilled adrenaline (epinephrine) syringes.
- 4. In facilities where Link brand of adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL is stocked facilities should:
 - Only use compatible connector and adaptor systems as listed in Link's Safety Alert. a.
 - Ensure the availability of additional stock or alternative adrenaline (epinephrine) products for b. emergency situations. Alternative adrenaline (epinephrine) products include adrenaline (epinephrine) 1 in 10,000 ampoules and Juno brand of adrenaline (epinephrine) 1 in 10,000 prefilled syringe 10 mL.
 - Report any malfunction failure of the Link brand of adrenaline (epinephrine) 1 in 10,000 prefilled C. syringe 10 mL in the facilities incident management system and to the TGA.
- Ensure a system is in place to document actions taken. 5.
- 6. Confirm receipt of this notice to CEC-MedicationSafety@health.nsw.gov.au